1.1.1.1

05-0155 000 6 of 7

15 october 1955

NRO REVIEW COMPLETED

DESCRIPTION OF THE RECORD

MEDICT: Prip Report to Atlantic Missile Test Center

and the undersigned proceeded to the Atlantic Missile Test Center at Cocca Heach, Florida, to observe the lunar probe shot scheduled for 11 October 1958. Cocca Heach, Florida, is located approximately 80 miles from Orlando on a large sand bar or reef connected to the mainland of Florida by a causaway across the Hamana River, a part of the inland waterway. Fatrick AFB is located at the south end of this sand bar with Cape Canaveral located on the north end of the sand bar about 20 miles distent from latrick AFB.

- 2. The group arrived at Cocos Beach in the efternoon of 9 October but was unable to contact Col. Methicon, BMD representative from California, until the morning of 10 Detober. At that time Col. Methicon introduced the group to Lt. Col. Wright who acted as the ascort on a tour of the Best Center.
- 3. Col. Wright first explained that Patrick AFD was more or less the housekeeping base for the Test Center while Cape Canaveral was the actual test range. To familiarise the party with past tests and the preparation for the lunar shot, Col. Wright gave a very thorough briefing with the aid of color slides and movies on past launchings and the make-up of the lunar vehicle. It was explained that the lunar vehicle was a four stage vehicle with a small satellite equipped with an ionization chamber for rediction measurement and a crude television camera for television relay pictures of the back side of the moon. The first stage of the rocket is a Thor missile. Manted on the Thur is a modified Vanguard second stage missile topped by a solid fuel third stage missile. After third stage burn out, the remaining actallite is given its final guidance by a ring of vermier rockets that correct the path of the package at that point. As the package enters the gravitational influence of the moon, about 2.6 days from the earth, the fourth stage or retrorocket is fired to allow down the satellite and enable it to go into orbit.
- of the Cape Conseveral site. He first explained that the Cape was broken

25X1

0077-0185 Frank 2

down into the test areas and the industrial area. The industrial area contains hanger and workshop space for all the contractors interested in the various mismiles tested at the site. The Central Control building is also located in the industrial area and acts as the nerve center of all test operations. Reports are received at this point from the many land tracking stations and ships down range as far as Assession Island, which is located in the Atlantic about midway between South America and Africa. The flight of the missile is monitored from Central Control by the range safety officer who is prepared to destroy the missile the minute its course deviation endangers any land mass.

- 5. The test sites at the Cape are memorous with launch pads for test of the Thor, Atlas, Titon, Polaris, Snark, Vanguard, Mavaho and Jupiter minelles. Each test pad and each hanger area in the industrial area is surrounded with a cyclone fence and guarded by a quard at the gate of the fence and one at the pad, or work area. Personnel movement is restricted by use of a badge system.
- 6. Guard services, as well as all other housekeeping services, are provided by Pan American Airlines which is under contract to the Air Force for these services as well as the services provided at the down range tracking stations. The guards are very alert and security control appears to be very good.
- 7. On the night of the lazerh the party proceeded first to the launch pad for a last minute look at the hunar vehicle. Although meximum security procedures were in force, it was noted that there was a large number of technicians and Air Force deservers at the launch site.

25X1

COM-CESS

base theater at Patrick AFR where a press conference was held with Dr. Silverstein of NASA, General O. J. Ritland of BMD, General Yates of the Atlantic Rest Site, Dr. Dunn of the Space Technology Laboratory and Dr. Dennett, Chief of Electronics for the lunar probe. The prese maked various questions on the probability of success. Manhars of the interviewed party explained that success could not be accurately predicted until all results were received from tracking sources. A few questions were asked about future projects. The conference asked to defer any comment on future use of missiles until the results of this flight could be evaluated. General Yates finally closed the conference and explained that all other releases would have to came from Washington.

- ). The handling of the security and press relations was very satisfactory for this launch. As was explained carlier, the proces was not allowed to observe the missile at close range or rose stored the base unescorted. The security and press relations teak was made relatively easy at this launch because of the fact that the launch was unclassified. Greater problems are foreseen in COROMA launches. At a CORONA Launch, photographs of the different stages could not be peaced out unless pictures of a purely instrumented peckage were make up and handed out prior to the CORONA launch. The latter method would probably be best as the precedent of handing out photos to the press has more or less been set at the Cape. It is also noted that followup releases furnished information on rediction measurement and temperature. Scientific information gathered as a result of the "instrumentation package in a CORONA vehicle should be given out in order to make the press news releases appear like any other scientific type shots. The fact that this shot was completely unclassified and everything exald be explained in detail to the press probably was responsible for the lack of speculation on future projects and possibility of other instrumentation in this particular shot.
- 10. The presence of minerous guards, uses of badge systems and necessity for adherence to various security procedures at Cape Canavaral neem to be unchallenged and treated as a necessary function. Consequently, the establishment of a maximum security atmosphere at vandemburg AVB should not appear inconsistent with past treatment at missile launch sites. The security system might have a week link in its treatment of visitors. It was mentioned that occasionally visitors from Washington, whose visits are authorized by the Department of Defence PIO function, are given the "grand tour" of the test site. This type tour could pose security problems. Other problems might arise due to the number of people actually involved in the entire operation. There were quite a few technicisms and observers at the launch site Just prior to launch time.

On-Olds

- Il. Frobably one of the biggest security problems that can be expected at Vandamburg AFE was demonstrated at the area surrounding the test site. This problem, which is always present in this type of operation, is the conduct of the workers and other knowledgeable people while they are sway from the test site. The technicisms, emiractor public relations types, Air Force personnel and members of the press seemed to congregate at the Starlite Motel at Cocoa Beach. Discussion at the Starlite usually turns to missile problems which are aired without too much regard for the press representatives within earshot.
- 12. All members of the visiting party felt that the trip was very interesting and extremely informative as the procedures established at Canavaral should be very similar to those to be used at Vandauburg.

Accistant Cover Officer
DPS/DCI

25X1

Dietribution:

1 - Cover/DPS

2 - SA/FD/DCI

3 - D & P/DPS

4 - Ops/DPS

5 - Secur/DPS

( - Admin/DPS

7 - Cover COR Chrono

25X1

nes/eci: